

TEST REPORT

No. : XMCCM160200156

Date: Feb.26, 2016

Page: 1 of 3

GUANDONG ITALIA s.r.l. S.s.415 Paullese Km 10

20090 CALEPPIO DI SETTALA (MI) ITALY

C.F. e P.IVA 05512420968

The following sample(s) was/ were submitted and identified on behalf of the client as:

Sample Name

Shop Sign

SGS Ref. No.

CP16-006658

Test Required

: Selected test(s) as requested by applicant

Date of Receipt

: Feb.22, 2016

Test Period

: Feb.22, 2016 to Feb.26, 2016

Test Result(s)

: For further details, please refer to the following page(s)

******* To be continued*******

Signed for

SGS-CSTC Standards Technical

Services Co., Ltd. XM Branch Testing Center

Civi Huang

Authorized Signatory



No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiannen, Fujian Province, China. 361101 1 (86-592) 5761588

f (86-592) 5765380



TEST REPORT

No. :

XMCCM160200156

Date:

Feb.26, 2016

Page:

2 of 3

Slip resistance (oil-wet ramp test)

Test Method:

DIN 51130:2014-02 Testing of floor coverings - Determination of the anti-slip property - Workrooms and fields of activities with slip danger, walking method - Ramp test

Sample Description:

Film, 8 pcs of specimens 295mm×210mm were pasted on polished ceramic tiles to form a testing surface 1180mm×420mm

Test Result:

Testing surface: see the photos

Test item(s)	Test result(s)	Classification
Slip resistance (oil-wet ramp test) Critical angle of inclination: 16.4°		R10

Appendix A: Classification of oil-wet ramp test

Classification	Angle (degrees)	
R9	6°≤X≤10°	
R10	10° <x≤19°< td=""></x≤19°<>	
R11	19° <x≤27°< td=""></x≤27°<>	
R12	27° <x≤35°< td=""></x≤35°<>	
R13	>35°	

******* To be continued******



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-and-Condit

中国・福建・厦门・火炬(帮安)产业区用虹路31号

邮编:381101 1 (86-592) 5761588

1588 f (86-592) 5765380 1588 f (86-592) 5765380

sgs.china@sgs.com



TEST REPORT

No. :

XMCCM160200156


Date:

Feb.26, 2016

Page:

3 of 3

Specimen photographs:



SGS authenticate the photos on original report only *******End of report******



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or access that of the company subject to its General Conditions of Service printed overleaf, available on request or access that of the company subject to Terms and Conditions for Elect Indomnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon refuse Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's size response transaction documents. This document cannot be reproduced except in full, without prior written approved of the Company. Any unaunto alteration, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the first of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sam suthenticity of testing Anspection report & conflicate, please contact us at telepho

Ct. LM No.31 Xienghang Road, Xieng'An Torch Industrial Zone, Xienen, Fujian Province, China. 361101 1 (86-592) 5761598 f (86-592) 5765390 www.sgsgroup.com.cn

中國·福建·厦门·火炬(翔安)产业区用缸路31号

邮桶:361101 t (88-592) 5761588

f (86-592) 5765390 e sçis.china@sgs.com